

NOTE: All beams attached to frames MUST be re-placed in their original locations.

NOTE: Verify damaged frame locations with Records Center Manager.

◇ Double Sided: Remove/replace beams from both sides of frame. All other frames remove/replace beams from one side of frame only.

NOTE: See Sheet A2.3 for Repair Schedule for this area.




It is the intent of this contract that all earthquake damage be repaired. Quantities shown herein shall form the basis of the Contractor's Base Bid and the Contract for Construction. If hidden damage in excess of that shown is found, notify the Architect immediately. DO NOT proceed with additional work without written authorization.



**State of Washington
Engineering and Architectural Services
FEMA Nisqually Earthquake Repairs**

**Modular and Record Center Buildings
7580/7590 New Market Street SW
Olympia, Washington 98504-0239**



email: chris@designplus-wa.com
**ARCHITECTURE ♦ INTERIOR DESIGN
 PROGRAMMING ♦ SPACE PLANNING**
 425.462.1210 FAX 425.462.0886
 1417 100th Avenue NE, Bellevue, Washington 98004-3523

DESIGN

2491 REGISTERED ARCHITECT
 Christina A. Johnson
 STATE OF WASHINGTON

BID DOCUMENTS

State Project
2002.161

Date Issued
8.2.2005

A1.8